

FACSIMILE COMMUNICATION FORM

**Port of Fujairah**

P.O. Box : 787, Fujairah
 United Arab Emirates
 Fax : 09-2228811 (Admin.)
 09-2228555 (Oprts.)
 09-2228312 (Engg.)
 09-2228022 (Marine)

ميناء الفجيرة

ص.ب : ٧٨٧ - الفجيرة
 الإمارات العربية المتحدة
 فاكس : ٩-٢٢٢٨٨١١ (الادارة)
 ٩-٢٢٢٨٥٥٥ (العمليات)
 ٩-٢٢٢٨٣١٢ (الهندسة)
 ٩-٢٢٢٨٠٢٢ (بحرية)

To:	All Agents / Bunkering Companies / Oil Terminal Users / Hydrographic Office - UK		
Attn:	General Manager / Operations Manager		
From:	Capt. Tamer Masoud- Harbour Master		
Facsimile No.:	City: Fujairah	Country:	U.A.E
Ref. No. MD/FAX/19/075	Date: 09 March 2019	No. Pages:	1

Notice To Mariners No. 255**SUBJECT : SPM CHANNEL BUOY # 4 MISSING**

Please be advised that the SPM Channel Buoy # 4 at position 25⁰ 18.4' N & 056⁰ 31.10'E is missing since 09 March 2019.

We are in the process of procuring a new SPM Channel Buoy and the position of Channel Buoy # 4 will remain vacant until the installation of new buoy.

Best Regards,


 Capt. Tamer Masoud,
HARBOUR MASTER.

C.c : Managing Director – PoF
 CFO - PoF
 Operations Manager – PoF
 Terminal Manager - PoF
 Dy. Harbour Masters - PoF
 Control Tower.