

PORT OF FUJAIRAHP.O BOX : 787, FUJAIRAH
United Arab EmiratesPhone : 09 2228777
09 2070808

Fax : 09 2228022

Email : ct_pof@fujairahport.ae
hm_pof@fujairahport.ae
mo_pof@fujairahport.ae

Port of Fujairah

**MARINE DEPARTMENT**

ميناء الفجيرة

ص.ب : 787 ، الفجيرة
الإمارات العربية المتحدةهاتف : 09 2228777
09 2070808

فاكس : 09 2228022

بريد إلكتروني : ct_pof@fujairahport.ae
hm_pof@fujairahport.ae
mo_pof@fujairahport.ae

To :	All Agents, Bunkering Companies, Coast Guard, FMA, UK Hydrographic Office				
Attn:	General Manager & Operations Manager				
From:	Capt. Mayed Alameeri – Harbour Master				
Ref. No.	MD/22/048	Date:	10 February 2022	No. Pages:	1 + 1

Notice to Mariner No. 310**SUBJECT : LATERAL BUOY – CHANGE OF POSITION**


Please be advised of the changes in the positions of lateral buoys at Vopak Terminal,

1. Lateral buoy at Position Lat. 25⁰ 12.705' N & Long. 056⁰ 22.006' E has been removed.
2. Lateral Buoy **MB11** at Position Lat. 25⁰ 12.640' N & Long. 056⁰ 21.95' E has been shifted to a new position Lat. 25⁰ 12.707' N & Long. 056⁰ 22.011' E.
3. Lateral Buoy **MB12** at Position Lat. 25⁰ 12.515' N & Long. 056⁰ 21.85' E has been shifted to a new position Lat. 25⁰ 12.523' N & Long. 056⁰ 21.885' E.
4. Lateral Buoy **MB13** at Position Lat. 25⁰ 12.01' N & Long. 056⁰ 21.872' E has been shifted to a new position Lat. 25⁰ 12.422' N & Long. 056⁰ 21.874' E.

Effected Charts: 3708 & 3709

Please advise all your principals accordingly.

Best Regards,

 10/2/22.

Capt. Mayed Alameeri
HARBOUR MASTER.

c.c : Managing Director – PoF
Dy. Managing Director – PoF
Marine Consultant – PoF
HSSE Manager – PoF
Port Security Officer - PoF
Asst. Harbour Master – PoF
Pilot Office
Control Tower