

**PORT OF FUJAIRAH**P.O BOX : 787, FUJAIRAH  
United Arab EmiratesPhone : 09 2228777  
09 2070808

Fax : 09 2228022

Email : ct\_pof@fujairahport.ae  
hm\_pof@fujairahport.ae  
mo\_pof@fujairahport.ae

Port of Fujairah

**MARINE DEPARTMENT****ميناء الفجيرة**ص.ب : 787 ، الفجيرة  
الإمارات العربية المتحدةهاتف: 09 2228777  
09 2070808

فاكس: 09 2228022

بريد إلكتروني: ct\_pof@fujairahport.ae  
hm\_pof@fujairahport.ae  
mo\_pof@fujairahport.ae

To :	<b>All Agents, Bunkering Companies, Coast Guard, FMA, UK Hydrographic Office</b>				
Attn:	<b>General Manager &amp; Operations Manager</b>				
From:	<b>Capt. Mayed Alameeri – Harbour Master</b>				
Ref. No.	<b>MD/22/394</b>	Date:	<b>12 October 2022</b>	No. Pages:	<b>1 + 1</b>

**Notice to Mariner No. 319****SUBJECT : FAIRWAY BUOY – CHANGE OF POSITION**

Please be advised that the Fairway Buoy which was in position 25<sup>0</sup> 08.0' N & 056<sup>0</sup> 25.0' E has been shifted 3 cables Southwards. The new position of the Fairway Buoy is given below,

Latitude : 25<sup>0</sup> 07.70' NLongitude : 056<sup>0</sup> 25.0' E.

Effected Charts: 3708, 3709 &amp; 3723.

A chartlet indicating the new position is attached.

Please advise all your principals accordingly.

Best Regards,

Capt. Mayed Alameeri  
**HARBOUR MASTER.**c.c : Managing Director – PoF  
Dy. Managing Director – PoF  
Marine Consultant –PoF  
HSSE Manager – PoF  
Port Security Officer - PoF  
Asst. Harbour Master – PoF  
Pilot Office  
Control Tower