
## FUJAIRAH PORT AUTHORITY DIBBA PORT

P.O.Box: 11777, Dibba, Fujairah, United arab Emirates

Tel.: 00971-9-2045580 E-mail: pc.dp@fujairahport.ae hm@fujairahport.ae mo\_pof@fujairahport.ae







ص.ب: ١١٧٧٧ دبا، الفجيرة الإمارات العربية المتحدة

نليفون: ۰۰۹۷۱-۹-۲۰۶۵۵۸۰ تليفون pc.dp@fujairahport.ae البريد الالكتروني: hm@fujairahport.ae mo\_pof@fujairahport.ae

To:	All Agents, Bunkering Companies, Coast Guard, FMA, UK Hydrographic Office				
Attn:	General Manager & Operations Manager				
From:	Capt. Mayed Alameeri – Harbour Master				
Ref. No.	MD/24/02	Date:	08 March 2024	No. Pages:	1 + 1

## Notice to Mariners No. 02

SUBJECT : INSTALLATION OF A GREEN LATERAL BUOY

IN DIBBA PORT MAIN HARBOUR

A new green lateral buoy has been installed in Dibba Port main harbour. The position of the buoy is given below

Latitude

25° 36.900' N

Longitude

056<sup>0</sup> 17.480' E.

This newly installed lateral buoy has been named as B9.

Also the buoy at position, Latitude 25°36.759' & Longitude 056°17.500' has been renamed to B9A.

A chartlet is attached indicating all the navigational aids in Dibba Port.

Please advise all your principals accordingly.

Thanks & Regards,

Capt. Mayed Alameeri

**HARBOUR MASTER** 

c.c. : Managing Director – PoF

Dy. Managing Director – PoF

Marine Consultant - PoF Dibba Port Manager

HSE Manager -PoF

Port Security Manager – PoF

Nautical Superintendent - PoF

Pilot Office

Control tower

Hydrographic Office UK.