

PORT OF FUJAIRAH

P.O.Box: 787, Fujairah,
United Arab Emirates

Tel.: 00971-9-2228777

: 00971-9-2070808

E-mail: ct_pof@fujairahport.ae
hm@fujairahport.ae
mo_pof@fujairahport.ae

Port of Fujairah



Port of Fujairah
United Arab Emirates

الإدارة البحرية
MARINE DEPARTMENT

ميناء الفجيرة

ص.ب: ٧٨٧ الفجيرة،
الإمارات العربية المتحدة

هاتف: ٠٠٩٧١-٩-٢٢٢٨٧٧٧

: ٠٠٩٧١-٩-٢٠٧٠٨٠٨

البريد الإلكتروني: ct_pof@fujairahport.ae
hm@fujairahport.ae
mo_pof@fujairahport.ae

To :	All Agents, Bunkering Companies, De-Sloping Companies, Oil Terminal Users, FMA, U.K Hydrographic Office, Coast Guard, Fujairah Marine Club, Fishermen's Association.			
Attn:	General Manager & Operations Manager			
From:	Capt. Eduardas Ringis – Acting Harbour Master			
Ref. No.	MD/26/229	Date:	19 August 2026	No. Pages: 1

Notice to Mariner No. 376**SUBJECT : RECLAMATION IN PROGRESS - MOVEMENT OF SPECIAL MARKS**

Further to our Notice to Mariners No. 369 Kindly note that two new Green Buoys has been established to mark the boundary of the entrance of Main Harbour. The location and characteristics of the Green Buoys are detailed below,

Special Mark Buoy

Buoy No.	Buoy's Position	Buoy's colour	Buoy's light	Range
G1	25° 10.254'N 056° 22.289'E	Green	FL(1) G 4s	4 NM
G2	25° 10.081'N 056° 22.376'E	Green	FL(1) G 4s	4 NM

In addition, the following Aids to Navigation moved to new coordinates as follows,

1. Yellow Special Marker Buoy (Y1) moved to 25° 10.082' N / 056° 22.575' E
2. Yellow Special Marker Buoy (Y3) moved to 25° 10.324' N / 056° 22.781' E
3. East Cardinal Buoy moved to 25° 10.082'N / 056° 22.819' E.

Positions of all other buoys at the reclamation area remain unchanged.

All Shipowners, agents, charterers, marinas, yacht clubs and fishermen shall ensure that the contents of this notice are communicated to the masters or persons in charge of their vessels.

Effected Charts : 3708, 3709 & 3723.

Regards,

Capt. Eduardas Ringis,
Acting Harbour Master.